



NOTES:

1. CUT-IN GATE VALVE SHOULD BE FULL BODY DUCTILE IRON.
2. ANCHOR BLOCKING PER AUD 1.15 DETAIL.

NO REVISION OR MODIFICATION OF THIS DETAIL SHALL BE MADE WITHOUT PRIOR WRITTEN APPROVAL FROM AUGUSTA UTILITIES DEPARTMENT.

REVISED: JANUARY 2018

**CUT-IN GATE VALVE OR TEE**

**AUD DETAIL 1.8**

**AUGUSTA UTILITIES DEPARTMENT**  
**452 WALKER STREET, SUITE 200**  
**AUGUSTA, GA 30901**

